



Firmware Release Notes

Version 1.4

[30-03-2024]

Project Number: HE 101341

Product Description: NCC-2222

This version contains full support for the RPS-UNI power supply.
For this version you need MIB1_8 or higher to work properly with TRAPS.

Technetix Ltd

Communications House, Edward Way, Burgess Hill, West Sussex RH15 9TZ, UK

Kazemat 5, NL-3905 NR, PO Box 385, NL-3900 AJ, Veenendaal, Netherlands

Technetix Ltd.	Class	Company Confidential	Doc No.	HE 101341 xx
	Title	FW Release Notes for NCC-2222 V1.4	Issue	0A
Page 1 of 2	Author	J. Janssen	Date	03-09-2018

Initial Release V1.4 (differences with NCC-2222 FW V1.3):

- *

Bug fixes:

- Copytool, copy reference value for NCI521/12, NCI321D(M).
-

Caution conditions:

- With installing this new firmware version, it's always better to reset the NCC-2222 with a Factory Default.
- The HEX switch on the RPS-UNI **MUST** match with the installed power supplies to get correct overcurrent warnings. There is not control line between the NCC-RPS to monitor if the HEX switch is correctly set by the technician because of short in hardware lines.
- When the Session on the Website is not saved or restored before the website is closed, the last position will stay active till:
1. Reboot of NCC-2222
2. Reopening the specific configuration Website address. When readout of the SNMP value is equal to the actual state or the last Website situation. Always press Save or Restore after closing the Web session. This can't be overruled automatically since Web is only a readout and not a host.

Technetix Ltd.	Class	Company Confidential	Doc No.	HE 101341 xx
	Title	FW Release Notes for NCC-2222 V1.4	Issue	0A
Page 2 of 2	Author	J. Janssen	Date	03-09-2018